




PART #	COMPONENT	QUANTITY
1	Top Cover	1
2	Button	1
3	PCBA Board	1
4	Battery	1
5	EVA Sheet	1
6	Motor	1
7	M3*4 Screw	3
8	Sleeve	1
9	M2*4 Flat Head Screw	4
10	Motor Bracket	1
11	Handle	1
12	10*3 Magnet	1
13	Connector	1
14	Handle Head	1
15	M6 Self-Locking Nut	1
16	Powder Metallurgy Oil-impregnated Copper Sleeve	1
17	Handle Shaft	1
18	Upper Adjustment Piece	1
19	Upper Washer	1
20	Bearing	1
21	Bearing Ring	1
22	Shaft	1
23	Adjustment Washer	1
24	Bearing	2
25	Main Body	1
26	Lower Washer	1
27	Spring	1
28	Connecting Ring	1
29	Spring	3
30	Seal Ring	2
31	Grinding Disc	1
32	Fixing Ring	1
33	Positioning Ring	1
34	Wave Ball Pin	2
35	Adjustment Ring	1
36	3*3 Magnet	24
37	Grinding Head	1
38	Grinding Head Washer	1
39	M4 Washer	1
40	M4*10 Screw	1
41	Powder Cup	1
42	Top Cover	1

